



6911 Marlin Circle. La Palma, Ca. 90623
(714) 523-8700, Fax (714) 523-3220

6911 Marlin Circle. La Palma, Ca. 90623
(714) 523-8700, Fax (714) 523-3220

IMPORTANT MOUNTING INFORMATION
FOR OPTIMUM PERFORMANCE YOU MUST INSTALL THE 3/8" FLAT WASHERS IN THE 2 POSITIONS SHOWN BELOW (ARROWS). ALSO MOUNT LINK AS SHOWN WITH MALE ROD END ATTACHED TO TRANSMISSION MOUNT.

IMPORTANT MOUNTING INFORMATION
FOR OPTIMUM PERFORMANCE YOU MUST INSTALL THE 3/8" FLAT WASHERS IN THE 2 POSITIONS SHOWN BELOW (ARROWS). ALSO MOUNT LINK AS SHOWN WITH MALE ROD END ATTACHED TO TRANSMISSION MOUNT.



FAILURE TO DO SO MAY CAUSE EXCESSIVE VIBRATION AND ROD END FAILURE

FAILURE TO DO SO MAY CAUSE EXCESSIVE VIBRATION AND ROD END FAILURE



6911 Marlin Circle. La Palma, Ca. 90623
(714) 523-8700, Fax (714) 523-3220

6911 Marlin Circle. La Palma, Ca. 90623
(714) 523-8700, Fax (714) 523-3220

IMPORTANT MOUNTING INFORMATION
FOR OPTIMUM PERFORMANCE YOU MUST INSTALL THE 3/8" FLAT WASHERS IN THE 2 POSITIONS SHOWN BELOW (ARROWS). ALSO MOUNT LINK AS SHOWN WITH MALE ROD END ATTACHED TO TRANSMISSION MOUNT.

IMPORTANT MOUNTING INFORMATION
FOR OPTIMUM PERFORMANCE YOU MUST INSTALL THE 3/8" FLAT WASHERS IN THE 2 POSITIONS SHOWN BELOW (ARROWS). ALSO MOUNT LINK AS SHOWN WITH MALE ROD END ATTACHED TO TRANSMISSION MOUNT.



FAILURE TO DO SO MAY CAUSE EXCESSIVE VIBRATION AND ROD END FAILURE

FAILURE TO DO SO MAY CAUSE EXCESSIVE VIBRATION AND ROD END FAILURE